




SHAD

HERO X PULSE 200 pro '26 TOP MASTER H0XP26ST

BCN



1 263831 x 1



2 260596 x 2
Ø16 Ø9 x 20



3 303017 x 12
Ø6



4 303099 x 6
Ø6




5 304201 x 2
M6x40 DIN 7380



6 304093 x 2
M6 x 40 DIN 7991



7 261042 x 2
Ø16 Ø9 x 15



8 263829 x 1
263830 x 1



9 304052 x 4
M6x20 DIN 7380

WARNING!

GB Do not fully tighten the screws until it is ensured that the KIT is correctly attached and aligned. Check tightness every 4 months..

E No apretar los tornillos del todo hasta asegurarse que el KIT está correctamente colocado y alineado. Repasar apriete cada 4 meses.

D Ziehen Sie die Schrauben nicht ganz fest, bevor Sie sich nicht vergewissert haben, daß der Bausatz korrekt eingestellt und ausgerichtet ist. Alle 4 Monate Drehmoment überprüfen

I Non stringere del tutto le viti fin tanto non si è sicuri che il kit è collocato correttamente e allineato. Controllare il serraggio delle viti ogni 4 mesi

F Ne pas serrer les vis avant d'être sûr que le KIT soit correctement positionné et ajusté. Vérifier le serrage des vis tous les 4 mois.



1



2



3



B - C - D - E

COMPONENTS
NOT INCLUDED
USE THOSE OF
TOP CASE