


SHAD

HONDA CB 750 HORNET '23 TOP MASTER H0CB73ST

BCN

1 263259 x1 →
263260 x1 ←

2 261121 x2
Ø20 Ø11 x18

3 303118 x2
Ø10

4 303025 x6
Ø10

5 304067 x2
M10/1,25x50 DIN 961

6 303020 x4
Ø8

7 303027 x4
Ø8

8 304039 x4
M8x40 DIN 7380

9 260648 x2
Ø16 Ø9 x5

WARNING!

GB Do not fully tighten the screws until it is ensured that the KIT is correctly attached and aligned. Check tightness every 4 months.

E No apretar los tornillos del todo hasta asegurarse que el KIT está correctamente colocado y alineado. Repasar apriete cada 4 meses.


D Ziehen Sie die Schrauben nicht ganz fest, bevor Sie sich nicht vergewissert haben, daß der Bausatz korrekt eingestellt und ausgerichtet ist. Alle 4 Monate Drehmoment überprüfen.

I Non stringere del tutto le viti fin tanto non si è sicuri che il kit è collocato correttamente e allineato. Controllare il serraggio delle viti ogni 4 mesi.


F Ne pas serrer les vis avant d'être sûr que le KIT soit correctement positionné et ajusté. Vérifier le serrage des vis tous les 4 mois.

ATTENTION: For a complete assembly of the equipment, assemble the top kit together with the cafe racer.

TOP MASTER



IMPORTANT: Based on European models.
For compatibility with models in other continents,
check www.shad.es



TOP MASTER + CAFE RACER

