


SHAD

RIEJU AVENTURA 500 '23

TOP MASTER R0VN53ST

BCN



1 263362 x 1




2 261117 x 4
Ø20 Ø12 x 16




3 303045 x 6
Ø8



4 302024 x 4
M8



5 304036 x 2
M8 x 45 DIN 7380



6 304032 x 2
M8 x 50 DIN 7991

WARNING!


GB Do not fully tighten the screws until it is ensured that the KIT is correctly attached and aligned. Check tightness every 4 months..

E No apretar los tornillos del todo hasta asegurarse que el KIT está correctamente colocado y alineado. Repasar apriete cada 4 meses.

D Ziehen Sie die Schrauben nicht ganz fest, bevor Sie sich nicht vergewissert haben, daß der Bausatz korrekt eingestellt und ausgerichtet ist. Alle 4 Monate Drehmoment überprüfen.

I Non stringere del tutto le viti fin tanto non si è sicuri che il kit è collocato correttamente e allineato. Controllare il serraggio delle viti ogni 4 mesi.

F Ne pas serrer les vis avant d'être sûr que le KIT soit correctement positionné et ajusté. Vérifier le serrage des vis tous les 4 mois.



WWW.SHAD.ES

IMPORTANT: Based on European models. For compatibility with models in other continen check www.shad.es

REF. 500479 Edition 1^a