


SHAD

MOTO MORINI SEIEMMEZZO STR/SCR '22- M0SM62SR

BCN

1 263240 x1 →
263241 x1 ←

2 261042 x4
Ø16 Ø9 x 15

3 303045 x4
Ø8

4 303027 x4
Ø8

5 304039 x4
M8x40 DIN 7380

WARNING!

GB Do not fully tighten the screws until it is ensured that the KIT is correctly attached and aligned. Check tightness every 4 months.

E No apretar los tornillos del todo hasta asegurarse que el KIT está correctamente colocado y alineado. Repasar apriete cada 4 meses.






D Ziehen Sie die Schrauben nicht ganz fest, bevor Sie sich nicht vergewissert haben, daß der Bausatz korrekt eingestellt und ausgerichtet ist. Alle 4 Monate Drehmoment überprüfen.

I Non stringere del tutto le viti fin tanto non si è sicuri che il kit è collocato correttamente e allineato. Controllare il serraggio delle viti ogni 4 mesi.

F Ne pas serrer les vis avant d'être sûr que le KIT soit correctement positionné et ajusté. Vérifier le serrage des vis tous les 4 mois.




ATTENTION: For a full equip assembly, mount the Top master after the Cafe Racer.

SEIEMMEZZO STR



IMPORTANT: Based on European models.
For compatibility with models in other continents, check www.shad.es

SEIEMMEZZO SCR



SEIEMMEZZO STR/SCR

CAFE RACER
+
TOP MASTER

