


SHAD

VOGE SR4 MAX '22 TOP MASTER V0SR42ST

BCN



1 263206 x1 →
263207 x1 ←



2 260712 x2
Ø20 Ø11 x 22



3 303045 x4
Ø8



4 304036 x4
M8x45 DIN 7380



5 260740 x2
Ø20 Ø11 x 11

WARNING!

(GB) Do not fully tighten the screws until it is ensured that the KIT is correctly attached and aligned.

(E) No apretar los tornillos del todo hasta asegurarse que el KIT está correctamente colocado y alineado.

(D) Ziehen Sie die Schrauben nicht ganz fest, bevor Sie sich nicht vergewissert haben, daß der Bausatz korrekt eingestellt und ausgerichtet ist.

(I) Non stringere del tutto le viti fin tanto non si è sicuri che il kit è collocato correttamente e allineato.

(F) Ne pas serrer les vis avant d'être sûr que le KIT soit correctement positionné et ajusté.

